



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Supervisor 1027

Inspection Report
Minerals Regulatory Program
Report Date: May 17, 2005

Mine Name: R & W Project
Operator or Permittee Name:
R & W Excavating, Inc
Permittee Mailing Address:
1475 West Field Avenue
P.O. Box 840830
Hilldale, Utah 84784

Permit number: S/053/074
Inspection Date: April 26, 2005

Inspector(s): Doug Jensen
Rody Cox, BLM
Other Participants: Ron Steed, R & W Excavating

Weather: Cool, Windy
Inspection Start Time: 1:15 PM
Inspection End Time: 2:00 PM
Site location/Area Inspected (i.e. Pit #):
Quarry
Surface Ownership: BLM
Mineral Ownership: BLM
Mineral Mined: Sandstone
Type of Mine: Quarry

Permit Status: Active
Current Acreages:
Total Permitted (Bonded): 1 Acre
Total Disturbed: 1 acre

Elements of Inspection	Evaluated	N/A	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (open shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Explosives, magazines	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Deleterious Material	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Concurrent Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Erosion Control	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Demolition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling and Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Facilities	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. Other	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Inspection Date: April 26, 2005; Report Date: May 17, 2005
Page 2 of 2
S/053/074

Purpose of Inspection:

This was a familiarization visit to the site for me.

Inspection Summary:

The site is a small quarry that is situated below a sandstone rock outcrop. The large boulders that are being mined from the outcrop is the material that R & W are removing from the site.

The disturbance at the site including the access road will total between 2 and 3 acres. Mr. Steed expressed some frustration with the site as the BLM has issued an additional permit to the south of their site that essentially cuts them off from following the outcrop. BLM agreed to investigating the possibility for them to move around this site and continue mining to the south. If an additional area was assigned to R & W, the area that they presently have disturbed would have to be reclaimed before they moved to the new area.

Photos were taken of the site and are included in this report.


Directions to the site:

The site is located ~ 10 miles south of Hurricane.

GPS data:

None gathered.

Inspector's Signature



Date: May 17, 2005

DJ:jb

Enclosures, photos

cc: Willie Jessop, Operator

Rody Cox, BLM, St George FO

O:\M053-Washington\S0530074-R&WProject\inspection\04262005insp.doc

